


At some point or other, you are going to produce a Revit model that is VERY big! And when that happens, there's a very good chance that the performance of Revit will start to creak. There are various things that you can do to help in this situation- one of them being the use of Worksets to reduce the working model size. **AECBytes** has a great article which discusses this very concept.



"The idea behind leveraging worksets to enhance performance is to break down a model into different categories and place elements of those categories into their respective worksets. In addition, every Revit link must have its own workset as well as a workset for all CAD links."

[Read the entire article here](#)